



SULLINS | MicroPlastics

760.744.0125 x 102 | fax 760.744.6081

801 E Mission Rd

San Marcos CA 92069

<http://www.Sullinscorp.com>

FORM  
DOC QF-7.3.7 Rev -

## ENGINEERING CHANGE BULLETIN

**ECB#: 10001**

**DATE: August 18, 2010**

### CUSTOMERS' NOTIFICATION OF PART NUMBER CHANGE

**Date Change Effective: August 20, 2010**

**Explanation of change from existing to new part number:**

Effective immediately Sullins Connector Solutions will change the termination designator for the .079" [2mm] CONTACT CENTER SMT Female Header Connector part number

**FROM: NPPN \_\_ 2GHN\_-RC TO: NPPN \_\_ 2GFN\_-RC**

### CUSTOMERS' NOTIFICATION OF PART NUMBER CONFIGURATION REVISIONS

**Date Change Effective: N/A**

**Explanation of configuration change/ (From) (To):**

**N/A**

**Configuration impacts for fit, form, and function are:**

The change is to indicate that the part can now be used in either a top or bottom entry configuration.

Anticipated impact on Form, Fit Function: Positive – Fully backwards compatible.

Changed parts can be identified by the part number call out on the accompanying shipping and packaging documents.

Parts can no longer be ordered or supplied with the GHN termination code.



SULLINS | MicroPlastics

760.744.0125 x 102 | fax 760.744.6081

801 E Mission Rd

San Marcos CA 92069

<http://www.Sullinscorp.com>

FORM  
DOC QF-7.3.7 Rev -


**ENGINEERING CHANGE BULLETIN**

**Existing parts will remain active for purchase?**

Yes  No

**New or revised parts are interchangeable to the previous part applications?**

Yes  No

Engineering Approval:  Date: 08/10/2010  
(Signature)

- Distribution:**
- Sales/Purchasing**
- Manufacturing Operations**
- Quality Assurance**
- Document Control**